History_en

2026/07/13

- Appl_x64
 - Updated NVCap to v1.5.5.7.
- Doc
 - Japanese
  - Updated SVL-03-UVC_Hardware_Specification_1.9
  - Updated SVL-03_FW_Release_Note.
  - Updated NVCap_Release_Note.
- FW_FPGA
 - Updated SVL-03-UVC_002_031_111_046_039_021_039_024.multi.
 - Updated SVL-03_UVC_V046_CuNV.fx10b.
 - Updated SVL-03_DP_TX_V021_CMNV.fx10c.

2026/05/01

- Appl_x64
  - Added SVLCtl v2.0.1.0, removed SVMCtl
  - Added SVLUpdater v2.0.1.0, removed SVMUpdater
  - Added SVCTL_API.dll v2.0.1.0, removed SVIO5API.dll
  - Added SVLCtl.ini, removed SVMCtl.ini
  - Added SVLUpdater.ini, removed SVMUpdater.ini
  - Updated PLLSetting to v1.0.1.0
- Doc
  - Japanese
    - Updated SVL-03-UVC_Hardware_Specification_1.8
    - Updated SVL-03_FW_Release_Note
    - Updated SVL-03_How to create a user resolution
    - Added SVLCtl_Release_Note
    - Added SVLCtl_Software_Manual_1.0
    - Added SVLUpdater_Software_Manual_1.0
    - Updated Differences between SVM-06 and SVL-03-UVC rev1.7
    - Added SV Series Control Library_SVCTL_API_Manual-V1.0
    - Added Device_Driver_Installation_Manual_1.0
  - English
    - Added How_to_Install_the_Device_Driver_1.0
    - Updated SVL-03-UVC_Hardware_Specification_1.1
    - Added SVLCtl_Software_Manual_1.0
    - Added SVLUpdater_Software_Manual_1.0
- Driver_x64
    - Added SviU3drv.dll
    - Added SviU3drv.inf
    - Added wudf.cat
- FW_FPGA
  - Updated SVL-03-UVC_002_031_111_043_039_020_039_024.multi
  - Updated SVL-03_DP_TX_V020_CMNV.fx10c
  - Updated SVL-03_Updater_V031_CbNV.fx10a
  - Updated SVL-03_UVC_V043_CuNV.fx10b
- Added Update_fx10a_bat

2026/02/27

- Appl_x64
  - Updated SVMCtl v1.7.9.4
  - Updated PLLSetting v0.9.4
  - Updated NVCap v1.5.5.6
- Doc
  - Japanese
    - Updated NVCap_Release_Note
    - Updated NVCap Software_Manual v1.93

    - Added PLLSetting_Operating Instructions v2.1
    - Updated SVL-03-UVC_Hardware_Specification_1.7
    - Added SVL-03_How to create a user resolution v1.0
    - Updated Differences between SVM-06 and SVL-03-UVC rev1.6
    - Updated SVMCtl_Release_Note
    - Updated SVMCtl_Software_Manual_12.0
    - Updated SVL-03_FW_Release_Note
  - English
    - Added How_to_Install_the_Device_Driver_1.1
    - Added NVCap_Software_Manual_1.30
    - Added SVL-03-UVC_Hardware_Specification_1.0
    - Added SVMCtl_Software_Manual_8.2
    - Added SVMUpdater_Software_Manual_1.0
- FW_FPGA
  - Updated SVL-03_DP_TX_V018_CMNV.fx10c
  - Updated SVL-03_UVC_V032_CuNV.fx10b
  - Updated svl_03_002_021_110_027_039_017_c39_v24.multi

2025/08/12

- Appl_x64
  - Updated SVMCtl v1.7.9.3
  - Updated NVCapx64.ini to the latest standard version of SVM-06
- Doc
  - Updated SVL-03-UVC_Hardware_Specification_1.6
  - Updated Differences between SVM-06 and SVL-03-UVC rev1.5
  - Updated SVL-03_FW_Release_Note
  - Updated SVMCtl_Release_Note
- FW_FPGA
  - Updated SVL-03_UVC_V028_CuNV.fx10b
  - Updated SVL-03_UVC_V111.fpgb
  - Added svl_03_002_021_111_028_039_017_c39_v24.multi

2025/07/02

- The following has been updated with the release:
- Appl_x64
  - Added PLLSettin.exe v0.9.3
  - Updated SVMCtl v1.7.9.1
  - Updated SVMUpdater v1.8.1.0
  - Updated SVI05API.dll v1.3.1.4
- Doc
  - Updated SVL-03-UVC_Hardware_Specification_1.5
  - Updated Differences between SVM-06 and SVL-03-UVC rev1.4
  - Updated SVMCtlSoftware_Manual_11.9
  - Updated How_to_Install_the_Device_Driver_1.4
  - Updated SVMUpdater Software_Manual_1.6
  - Updated SVL-03_FPGA_Release_Note
  - Updated SVL-03_FW_Release_Note
- FW_FPGA
  - Updated SVL-03_UVC_V110.fpgb
  - Added SVL-03_DP_TX_V039.fpgc
  - Added SVL-03_DP_TX_V039_CorlorBar.fpgd
  - Updated SVL-03_Updater_V021_CbNV.fx10a
  - Updated SVL-03_UVC_V027_CuNV.fx10b
  - Added SVL-03_DP_TX_V017_CMNV.fx10c
  - Added svl_03_002_021_110_027_039_017_c39_v24.multi
- Runtime
  - Added dotnet-sdk-9.0.202-win-x64.exe

2025/03/12

- Removed the HDMI mode description in Readme.txt

2025/01/09

- Initial Released