

History_en

2026/02/27

- Appl_x64
 - Updated SVMCtl v1.7.9.4
 - PLLSetting
 - Updated NVCap v1.5.5.6
- Doc
 - Japanese
 - Updated NVCap_Release_Note
 - Updated NVCap_Software_Manual v1.93
 - Added PLLSetting_Operating_Instructions v2.1
 - Updated SVL-03-UVC_Hardware_Specification_1.7
 - Added SVL-03_How_to_create_a_user_resolution v1.0
 - Updated Differences_between_SVM-06_and_SVL-03-UVC rev1.6
 - Updated SVMCtl_Release_Note
 - Updated SVMCtl_Software_Manual_12.0
 - Updated SVL-03_FW_Release_Note
 - English
 - Added How_to_Install_the_Device_Driver_1.1
 - Added NVCap_Software_Manual_1.30
 - Added SVL-03-UVC_Hardware_Specification_1.0
 - Added SVMCtl_Software_Manual_8.2
 - Added SVMUpdater_Software_Manual_1.0
- FW_FPGA
 - Updated SVL-03_DP_TX_V018_CMNV.fx10c
 - Updated SVL-03_UVC_V032_CuNV.fx10b
 - Updated svl_03_002_021_110_027_039_017_c39_v24.multi

2025/08/12

- Appl_x64
 - Updated SVMCtl v1.7.9.3
 - Updated NVCapx64.ini to the latest standard version of SVM-06
- Doc
 - Updated SVL-03-UVC_Hardware_Specification_1.6
 - Updated Differences_between_SVM-06_and_SVL-03-UVC rev1.5
 - Updated SVL-03_FW_Release_Note
 - Updated SVMCtl_Release_Note
- FW_FPGA
 - Updated SVL-03_UVC_V028_CuNV.fx10b
 - Updated SVL-03_UVC_V111.fpgb
 - Added svl_03_002_021_111_028_039_017_c39_v24.multi

2025/07/02

- The following has been updated with the release:
- Appl_x64
 - Added PLLSettin.exe v0.9.3
 - Updated SVMCtl v1.7.9.1
 - Updated SVMUpdater v1.8.1.0
 - Updated SVI05API.dll v1.3.1.4
- Doc
 - Updated SVL-03-UVC_Hardware_Specification_1.5
 - Updated Differences_between_SVM-06_and_SVL-03-UVC rev1.4
 - Updated SVMCtlSoftware_Manual_11.9
 - Updated How_to_Install_the_Device_Driver_1.4
 - Updated SVMUpdater_Software_Manual_1.6
 - Updated SVL-03_FPGA_Release_Note
 - Updated SVL-03_FW_Release_Note
- FW_FPGA
 - Updated SVL-03_UVC_V110.fpgb
 - Added SVL-03_DP_TX_V039.fpgc
 - Added SVL-03_DP_TX_V039_CorlorBar.fpgd

- Updated SVL-03_Updater_V021_CbNV.fx10a
- Updated SVL-03_UVC_V027_CuNV.fx10b
- Added SVL-03_DP_TX_V017_CMNV.fx10c
- Added svl_03_002_021_110_027_039_017_c39_v24.multi
- Runtime
 - Added dotnet-sdk-9.0.202-win-x64.exe

2025/03/12

- Removed the HDMI mode description in Readme.txt

2025/01/09

- Initial Released