

History_en

2026/05/01

- Appl_x64
 - Updated NVFilePlayer to v2.0.0.0
 - Updated PLLSetting to v1.0.1.0
 - Added SVLCtl v2.0.1.0, removed SVMCtl
 - Added SVLUpdater v2.0.1.0, removed SVMUpdater
 - Added SVCTL_API.dll v2.0.1.0, removed SVI05API.dll
 - Added SVLCtl.ini, removed SVMCtl.ini
 - Added SVLUpdater.ini, removed SVMUpdater.ini
 - Updated TimingGenSV006 to v2.0.0.0
- Doc
 - Japanese
 - Added NVFilePlayer_PatternGenerator_Manual v1.1
 - Updated NVFilePlayer_Release_Note
 - Updated NVFilePlayer_Software_Manual_rev3.0
 - Updated PLLSetting_Operating_Instructions v2.1
 - Updated SVL-03-GEN_Hardware_Specification_1.1
 - Updated Differences between SVL-03-GEN and SV0-03-MIPI/SV0-06 rev1.1
 - Updated SVL-03_FW_Release_Note
 - Added SVLCtl_Release_Note
 - Added SVLCtl_Software_Manual_1.0
 - Added SVLUpdater_Software_Manual_1.0
 - Added SV Series Control Library_SVCTL_API_Manual-V1.0
 - Updated TimingGen_Software_Manual_V1.7
 - Added Device_Driver_Installation_Manual_1.0
 - English
 - Added How_to_Install_the_Device_Driver_1.0.pdf
 - Updated SVL-03-UVC_Hardware_Specification_1.1.pdf
 - Added SVLCtl_Software_Manual_1.0.pdf
 - Added SVLUpdater_Software_Manual_1.0.pdf
- Driver_x64
 - Added SviU3drv.dll
 - Added SviU3drv.inf
 - Added wudf.cat
- FW_FPGA
 - Updated SVL-03-GEN_002_031_100_030_030_040_000.multi
 - Updated SVL-03_DP_RX_V040_CHNV.fx10c
 - Updated SVL-03_Updater_V031_CbNV.fx10a
 - Updated SVL-03_USB_V030_CONV.fx10b
- Added Update_fx10a_bat

2026/01/26

- Initial Released